

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor Kathleen Clarke Executive Director Lowell P. Braxton Division Director 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

Partial: XXX Con	nplete:	Exploration:		
Inspection Date & Time:	10/16/2000 /	11:00a.m1:00p.m.		
Date of Last Insp	ection: 9/14/	/2000		

Mine Name: Crandall Canyon Mine County: Emery Permit Number: ACT/015/032								
Permittee and/or Operator's Name: Genwal Resources, Inc.								
Business Address: P.O. Box 1420, Huntington, Utah 84528								
Type of Mining Activity: Underground XXX Surface Prep. Plant Other								
Company Official(s): Gary Gray								
State Official(s): Bill Malencik Federal Official(s): None								
Weather Conditions: Clear, 60's								
Existing Acreage: Permitted 5195.8 Disturbed 10.7 Regraded Seeded Seeded								
Status: Exploration Active XXX Inactive Temporary Cessation Bond Forfeiture								
Reclamation (Phase I Phase II Final Bond Release Liability Year)								

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL	EVALUATED [L] [X]	<u>N/A</u> [] [] []	COMMENTS [X] [X]	NOV/ENF
4.	HYDROLOGIC BALANCE: a. DIVERSIONS b. SEDIMENT PONDS AND IMPOUNDMENTS c. OTHER SEDIMENT CONTROL MEASURES d. WATER MONITORING e. EFFLUENT LIMITATIONS	[X] [X] [] []		[X] [X] [X] []	
5. 6. 7. 8. 9.	EXPLOSIVES DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	[<u>X]</u>			
11. 12. 13. 14.	SLIDES AND OTHER DAMAGE CONTEMPORANEOUS RECLAMATION BACKFILLING AND GRADING REVEGETATION SUBSIDENCE CONTROL CESSATION OF OPERATIONS ROADS:				
17. 18. 19. 20.	a. CONSTRUCTION/MAINTENANCE/SURFACING b. DRAINAGE CONTROLS OTHER TRANSPORTATION FACILITIES SUPPORT FACILITIES/UTILITY INSTALLATIONS AVS CHECK (4 th Quarter- April, May, June) AIR QUALITY PERMIT BONDING & INSURANCE				

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 10/16/2000

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

GENERAL COMMENTS

There was snow on the north side at the mine. Two areas were noted for routine maintenance. They are as follows:

- -Non-coal waste was in need of routine maintenance. Most appeared to be items that blew out of the coal waste storage area.
- -On the lower topsoil pile, a segment of the silt fence needed routine maintenance.

2. SIGNS AND MARKERS

Identification signs meet the requirements of the R645 Coal Rules.

The perimeter markers were spot-checked and are located around the perimeter of the disturbed areas. The permittee has stream buffer zone signs placed within the disturbed area. Topsoil ID signs are located on the topsoil piles as required in the R645 Coal Rules.

3. TOPSOIL

The topsoil piles were inspected with no signs of wind or water erosion. These piles are protected by berms and/or silt fences. Grass has started to grow on the newest topsoil pile.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were spot-checked and were found to comply with the requirements of the Mining and Reclamation Plan and the R645 Coal Rules performance standards.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond was not discharging during the inspection and the water level was low. There were no signs of any hazardous conditions occurring to the sediment ponds during the inspection. The Annual Sediment Pond inspection was done on December 27, 1999.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Genwal Mine uses straw bales, silt fences, and berms as its alternate sediment control measures. These areas were spot-inspected and complied with the R645 Coal Rules. Work on the silt fences was pointed out as an area in need of routine maintenance.

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION: 10/16/2000

8. NONCOAL WASTE

Some small non-coal waste was noted. Mr. Gray stated he would notify the surface foreman about this problem. This material is being stored in dumpsters and concrete storage bins.

13. REVEGETATION

Susan White asked the question about the reclaimed area. Her questions was in regards to the seed mix. Was it permanent or interim? Mr. Gray said it didn't matter since the area would be redisturbed.

The vegetal cover is primarily grasses. There are two areas: one above the portal and one below the portal. Since the area is to be redisturbed in final reclamation, it is a moot point and is considered interim vegetation.

18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

Observed the surface facilities and the comparison with the approved map was checked and was found to be correct.

Inspector's Signature: Mm. J. Malencik #26

Date: October 24, 2000

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd cc:

James Fulton, OSM

Gary Gray, Genwal Price Field office

 $O: \label{lem:compliance} O: \label{lem:co$